

Oil Field Environmental Incident Summary

Incident: 20160306172422 **Date/Time of Notice:** 03/06/2016 17:24

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: ALFSVAAG 2-31H

Field Name:

Well File #: 28936

Date Incident: 3/6/2016

Time Incident: 02:00

Facility ID Number:

County: WILLIAMS

Twp: 153

Rng: 99

Sec: 31

Qtr:

Location Description:

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 3/8/2016

Risk Evaluation:

None

Areal Extent:

30 ft x 50 ft on well site

Potential Environmental Impacts:

Location soil

Action Taken or Planned:

Well was shut in and valve will be replaced. Contaminated material was removed and disposed of.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 3/7/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on constructed well site according to the report. NDIC retains oversight.